

Inspection Photos
Location Name: Ray 1
Location ID: 317539



Pic 1 wellhead

Pic 2 Wellhead sign missing on wellhead

Inspection Photos
Location Name: Ray 1
Location ID: 317539



Pic 3 Separator, weeds unmanaged on location

Pic 4 GMR

Inspection Photos
Location Name: Ray 1
Location ID: 317539



Pic 5 tanks

Pic 6 Location sign

Inspection Photos
Location Name: Ray 1
Location ID: 317539



Pic 7 Machinery

Pic 8 spill location

Inspection Photos
Location Name: Ray 1
Location ID: 317539



Pic 9 Tank



Pic 10 tanks

Inspection Photos
Location Name: Ray 1
Location ID: 317539



Pic 11 Berms inadequate on location

Pic 12 berms

Inspection Photos
Location Name: Ray 1
Location ID: 317539



Pic15 Trailer on location



Pic 16 weeds unmanaged, berms not adequate.

Inspection Photos
Location Name: Ray 1
Location ID: 317539



Pic 17