

Inspection Photos
Location Name: Facility 5
Loc ID 159787/Spill ID 492917



Attempted condensate sampling from Facility 5 Gas Sales Line – No condensate produced



Attempted condensate sampling from Facility 5 Gas Sales Line – No condensate produced



Inspection Photos
Location Name: Facility 5
Loc ID 159787/Spill ID 492917



Facility 5 Gas Sales line



Oil Sampling from Facility 5 Horizontal Separator Oil Sight Glass

Inspection Photos
Location Name: Facility 5
Loc ID 159787/Spill ID 492917



Oil Sampling from Facility 5 Horizontal Separator Oil Sight Glass

