

Inspection Photos
Ray No 1 Tank Battery
Location ID 317539



Photo 1 – Location sign



Photo 2 – Spill observed around AST

Inspection Photos
Ray No 1 Tank Battery
Location ID 317539



Photo 3 – Spill observed around AST

Photo 4 – Spill observed around AST

Inspection Photos
Ray No 1 Tank Battery
Location ID 317539



Photo 5 – Spill observed around AST



Photo 6 – Spill observed around AST