

INSPECTION PHOTOS

Well: CULVER 14-12

API #: 05-071-08386

INSPECTION DOC #: 716302283

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 5/4/2026

County: Las Animas



Network: May 4, 2026 at 1:30:55 PM MDT
Local: May 4, 2026 at 1:30:55 PM MDT
+37.267758 -104.737087

PHOTO 2: WELL SIGN



Network: May 4, 2026 at 1:29:11 PM MDT
Local: May 4, 2026 at 1:29:11 PM MDT
+37.267549, -104.737339

PHOTO 3: LOCATION.



Network: May 4, 2026 at 1:30:32 PM MDT
Local: May 4, 2026 at 1:30:32 PM MDT
+37.267617, -104.736902
50° NE

PHOTO 4: WELLHEAD AND EQUIPMENT.



Network: May 4, 2026 at 1:30:24 PM MDT
Local: May 4, 2026 at 1:30:24 PM MDT
+37.267646, -104.736878
21° NE

PHOTO 5: IMPACTED SOIL HAS BEEN REMOVED.



PHOTO 6: TR WELLHEAD AND EQUIPMENT.



Network: May 4, 2026 at 1:29:42 PM MDT
Local: May 4, 2026 at 1:29:42 PM MDT
+37.267699, -104.737212
205° NW

PHOTO 7: AREA OF IMPACTED SOIL NEAR TR WELL COMPRESSOR. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 6/4/2026.