

INSPECTION PHOTOS

Well: DALLAS 44-13 & TR

API #: 05-071-08772, 09147

INSPECTION DOC #: 716302278

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 5/4/2026

County: Las Animas



Network: May 4, 2026 at 11:42:17 AM MDT
Local: May 4, 2026 at 11:42:17 AM MDT
+37.251295 -104.725836

PHOTO 2: WELL SIGN



Network: May 4, 2026 at 11:39:19 AM MDT
Local: May 4, 2026 at 11:39:19 AM MDT
+37.251185,-104.726419

PHOTO 3: LOCATION.



Network: May 4, 2026 at 11:41:17 AM MDT
Local: May 4, 2026 at 11:41:17 AM MDT
+37 251360, -104 725937
295° SW

PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: TR WELLHEAD AND EQUIPMENT.