

Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722



Photo #1

Owl Creek 13 (123-11934) Wellsite

Temporarily Abandoned | TA

CA: Signage w/ Emergency #, **NOT** posted

prior photo



Photo #2

Owl Creek 13 Wellsite

Temporarily Abandoned | TA

Signage w/ Emergency #, **NOW** posted

Operator photo: 04/21/2026



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722



Photo #3

Owl Creek 13 Wellsite

Temporarily Abandoned | TA

Macro view

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: OWL CREEK-67N64W/29NWNW

Location ID: 322722



Photo #4

Owl Creek 13 Battery site

Inactive | Shut-down

Equipment Documented; Loc ID: 322722

prior photo



Photo #5

Owl Creek 13 Battery site

Inactive | Shut-down

Well(s), Battery site entrance

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources