

Inspection Photos

Location Name: BASHOR PC AA/09-23

Location #: 420598



Photo #1

Bashor PC AA 09-23 (123-32644) Wellsite

Temporarily Abandoned | TA

CA: Signage w/ Emergency #, NOT posted

CA: Undesirable weeds

prior photo



Photo #2

Bashor PC AA 09-23 Wellsite

Temporarily Abandoned | TA

macro view

CAs: See photo #1

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: BASHOR PC AA/09-23

Location #: 420598



Photo #3

Bashor PC AA 09-23 Wellsite

Temporarily Abandoned | TA

Undesirable weeds; Mitigated

Operator photo: 04/01/2026



Photo #4

Bashor PC AA 09-23 Wellsite

Temporarily Abandoned | TA

Signage w/ Company, Well name,

Emergency #, NOW posted

Operator photo: 04/21/2026



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: BASHOR PC AA/09-23

Location #: 420598



Photo #5

Bashor PC AA 09-23 Wellsite

Temporarily Abandoned | TA

Wellsite(s) entrance

prior photo



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Location Name: BASHOR PC AA/09-23

Location #: 420598



Photo #6

Bashor PC AA 09-08, 09-23 Battery site

Inactive | Shut-down

Equipment Documented; Fac ID: 481647

Formerly served:

*Bashor PC AA 09-22; Plugged & Abandoned | PA
prior photo*



Photo #7

Bashor PC AA 09-08, 09-23 Battery site

Inactive | Shut-down

Battery entrance

prior photo



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources