

Inspection Photos
Location Name: UPRR-HOLMQUIST #1-1
Location ID: 319647



Photo #1 Tanks.



Photo #2 P/W tank.

Inspection Photos
Location Name: UPRR-HOLMQUIST #1-1
Location ID: 319647



Photo #3 ECD & Separator.



Photo #4 Pump jack.

Inspection Photos
Location Name: UPRR-HOLMQUIST #1-1
Location ID: 319647



Photo #5 stained soil around well head.