

Inspection Photos

04/22/2026

Operator: KP KAUFFMAN COMPANY INC - #46290

Location ID: 450391

Inspection Document #: 712300300

Jackson County, CO

Logan Maxwell
Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Make up water Tank Battery
Location ID: 450391



Photo 1. Photos 1-2 taken of the tank battery with drone imagery, illustrating the fiberglass patch.



Photo 2. See comments under photo 1.

Inspection Photos

Location Name: Make up water Tank Battery

Location ID: 450394



Photo 3. Photo taken from the northeastern portion of the tank battery, facing southwest, illustrating overview.



Photo 4. Photos 4-5 taken of the fiberglass patch on the tank.

Inspection Photos
Location Name: Make up water Tank Battery
Location ID: 450391



Photo 5. See comment under Photo 4.



Photo 6. Photo taken from the northeastern portion of the tank battery, facing south, illustrating some of the contaminated soil has been excavated underneath the tank battery.

Inspection Photos
Location Name: Make up water Tank Battery
Location ID: 450391



Photo 7. Photos 7-8 taken on the south of the tank batteries, facing northeast. Photos illustrate the free-standing fluids between the two tanks.



Photo 8. See comments under photo 7.

Inspection Photos

Location Name: Make up water Tank Battery

Location ID: 450391



Photo 9. Photos 9-10 taken of the honey pot and uncovered container on the northern side of the tanks, outside the berm. Both have fluids; the container in photo 10 had no protective covers.



Photo 10. See comments under photo 9.

Inspection Photos
Location Name: Make up water Tank Battery
Location ID: 450391



Photo 11. Photos 11-15 taken throughout the Location, illustrating stained and contaminated soils.



Photo 12. See comments under photo 11.

Inspection Photos
Location Name: Make up water Tank Battery
Location ID: 450391



Photo 13. See comments under photo 11.



Photo 14. See comments under photo 11.

Inspection Photos
Location Name: Make up water Tank Battery
Location ID: 450391



Photo 15. See comments under photo 11.



Photo 16. Photos 16-20 illustrated what appears to be the excavated contaminated soil from within the berm during the first spill. The soil is not stored adequately on the additional liner.

Inspection Photos
Location Name: Make up water Tank Battery
Location ID: 450391



Photo 17. See comments under photo 16.



Photo 18. See comments under photo 16.

Inspection Photos
Location Name: Make up water Tank Battery
Location ID: 450391



Photo 19. See comments under photo 16.



Photo 20. See comments under photo 16.



Inspection Photos

Location Name: Make up water Tank Battery

Location ID: 450391




Photo 21. Photos 21-22 illustrate that trash/debris/unused equipment was observed on the Location.



Photo 22. See comments under photo 21.



Inspection Photos

Location Name: Make up water Tank Battery

Location ID: 450391



Photo 24. See comments under photo 23.

Photo 23. Photos 23-24 taken on the northwestern and southwestern portions of the tank batteries, facing southeast and northeast, respectively. Photos illustrate the berm size and vegetation growth within the secondary containment.



Inspection Photos

Location Name: Make up water Tank Battery

Location ID: 450391



Photo 25. Photos 25-26 illustrate examples of vegetative growth on the earthen berms, illustrating the berms are not impervious to spills.



Photo 26. See comments under photo 25.

