

FORM
INSPRev
X/20

State of Colorado Energy and Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/23/2026

Submitted Date:

04/29/2026

Document Number:

693809242

FIELD INSPECTION FORM

Loc ID 334170	Inspector Name: BROWNING, CHUCK	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input checked="" type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 16 Number of Comments 4 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: 10841 Name of Operator: AMERICAN HELIUM LLC Address: 23501 CINCO RANCH BLVD, B244 City: KATY State: TX Zip: 77494				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Harrison, Trish	970-759-9545	trish.harrison@coolskyenergy.com	
Lapham, Ken	979-877-4951	klapham@americanhelium.us	All Inspections
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
Labowskie, Steve		steve.labowskie@state.co.us	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277440	WELL	SI	07/01/2023	GW	113-06178	HC STATE 36-14-45-15	TA
278538	WELL	SI	01/01/2025	GW	113-06191	HC FED 31-11-45-14	TA
278541	WELL	SI	06/01/2023	GW	113-06188	HC FED 31-21-45-14	TA

General Comment:

[ECMC Inspection/Audit Report Summary](#)

On April 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the HC STATE-N45N15W #36NEN padl, API# 113-06178/ 113-06188/ 113-06191, Loc ID#334170, in San Miguel County, Colorado.

The well was Temporarily Abandoned

During the inspection/audit, the following compliance issues were observed:
 1) Wrong API# on sign - 605.g - CA from Inspection Doc#693807550 dated 7/30/2024 not completed.
 2) Past Due MITs (3 wells) - 319.b

Any corrective action(s) from previous inspection that have not been addressed are still applicable

Location			
Lease Road:			
Type	Access		
comment:	U29 Rd to W Hamilton		
Corrective ActionL		Date:	
Type	Main		
comment:	Hwy 141		
Corrective ActionL		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	CA for Inspection Doc#693807550 dated 7/30/2024 completed.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Sign on meter housing for HC FED #31-11-45-14 has wrong API#. CA for Inspection Doc#693807550 dated 7/30/2024 not completed. CA date remains the same.		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	09/01/2024
Emergency Contact Number:			
Comment:	435-631-2239 CA for Inspection Doc#693807550 dated 7/30/2024 completed.		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Panel fence		
Corrective Action:		Date:	
Equipment:			
Type: Deadman # & Marked	# 6		corrective date
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:	Disconnected and blind flanged		
Corrective Action:		Date:	
Type: Plunger Lift	# 3		
Comment:			

Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Disconnected and blind flanged		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Line heater (unused)		
Corrective Action:		Date:	
Type: Bradenhead	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	STEEL AST		,-108.465702
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Wells Served By Facilities Above

API Number
113-06188
113-06191
113-06178

AirsID

API Number	AirsID

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	

Corrective Action:

Date:

Inspected Facilities

Facility ID: 277440 Type: WELL API Number: 113-06178 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Production 06/30/2023. No MIT on record.
Well was found in state of Temporary Abandonment.
Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. **Date:** 05/31/2026

BradenHead

Date of Last Brhd Test: 06/26/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ **Date:** _____

Facility ID: 278538 Type: WELL API Number: 113-06191 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Production 12/31/2024. No MIT on record.
Well was found in state of Temporary Abandonment.
Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. **Date:** 05/31/2026

BradenHead

Date of Last Brhd Test: 12/16/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ **Date:** _____

Facility ID: 278541 Type: WELL API Number: 113-06188 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last Production 05/31/2023. No MIT on record.
Well was found in state of Temporary Abandonment.
Well is overdue for Mechanical Integrity Test (MIT) MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Well can only be returned to SI status if it has produced (without mechanic intervention) within 2 years per Rule 319.b.

Corrective Action: Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210. **Date:** 05/31/2026

BradenHead

Date of Last Brhd Test: 06/25/2025 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE
End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ **Date:** _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Gravel	Pass			
Gravel	Pass	Ditches	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
<p>On April 23, 2026, ECMC Compliance Specialist Chuck Browning, conducted an onsite inspection for AMERICAN HELIUM LLC 10481 on the HC STATE-N45N15W #36NEN padI, API# 113-06178/ 113-06188/ 113-06191, Loc ID#334170, in San Miguel County, Colorado.</p> <p>The well was Temporarily Abandoned</p> <p>During the inspection/audit, the following compliance issues were observed: 1) Wrong API# on sign - 605.g - CA from Inspection Doc#693807550 dated 7/30/2024 not completed. 2) Past Due MITs (3 wells) - 319.b</p>	browninc	04/29/2026

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404639418	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7530843
693809253	Inspection photos 4/23/2026	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7530841