

Inspection Photos

API: 071-08860

Operator: EVERGREEN NATURAL
RESOURCES LLC

Inspection Date: 5/4/2026

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing south at the beginning of the reclaimed former road.



Inspection Photos



Photo 2. Facing southeast. This area has not established vegetation and needs additional seeding.



Inspection Photos



Photo 3. Facing southeast. There is an erosion channel and additional seeding should be performed.



Inspection Photos



Photo 4. Facing southwest.



Inspection Photos



Photo 5. Facing northwest at south side of the location. This area has not established vegetation and needs additional seeding.



Inspection Photos



Photo 6. Facing northwest at the north side of the location.

