

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SENE  
Facility # 324025**



**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SENE  
Facility # 324025**



**Tank rusted around seams.**



**Rusted pinholes around bottom tank valve.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SENE  
Facility # 324025**



**Tank rusted around seams.**



**Tank rusted around seams.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SENE  
Facility # 324025**



**Tank rusted around seams.**



**Tank top seam rusted through.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SENE  
Facility # 324025**



**Tank top seem rusted through.**



**Rusted pin holes on top of tank.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SENE  
Facility # 324025**



**Rusted pin holes on top of tank.**



**Rusted pin holes on top of tank.**

**QB ENERGY OPERATING LLC  
BENTLEY-67S95W 11SENE  
Facility # 324025**



**Rusted pin holes on top of tank.**



**Tank top seem rusted through.**