

**FORM
INSP**

Rev
X/20

**State of Colorado
Energy and Carbon Management Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/29/2026

Submitted Date:

04/30/2026

Document Number:

710500779

FIELD INSPECTION FORM

Loc ID 439367 Inspector Name: Sanchez, Chris On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 10412
Name of Operator: AUSCO PETROLEUM INC
Address: 113 N SANTA FE AVENUE
City: FLORENCE State: CO Zip: 81226

Findings:

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Hart, Tim	309-999-5420	thart@fremontpetroleum.com	All Inspections
Harkins, Liz	719-429-4513	Lharkins@austineexploration.com	All Inspections
Waggoner, Kyle		kyle.waggoner@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
439366	WELL	PA	07/31/2025	OW	043-06227	Columbus 1	EI

General Comment:

This is a follow up Environmental Inspection for the Columbus 1 well location located in Fremont County, Colorado

API # 05-043-06227
Location ID 439367
Pathfinder C-18 8
Remediation Project # 41043
Inspection # 710500676
Inspection # 710500727

Inspected Facilities

Facility ID: 439366 Type: WELL API Number: 043-06227 Status: PA Insp. Status: EI

Environmental

Spill/Remediation:

Comment: This is a follow up Environmental Inspection for Remediation Project # 41043.
 At the time of inspection, the wellhead excavation was backfilled.
 Operator has not provided analytical data for Remediation Project # 41043 to confirm the presence or absence of impact to soils within the wellhead excavation.
 Initial Form 27-I was submitted on 06/18/2025 and approved on 06/30/2025. The approved reporting schedule was identified as 90 days after receipt of analytical. Form 6-S document no. 404300603 indicates the well was cut and capped on 7/31/2025.
 Operator shall submit a Supplemental Form 27-S in accordance with the reporting schedule approved in Form 27-I document no. 404300603.

Corrective Action: Previously assigned corrective action date shall apply 01/30/2026 Date: 01/30/2026

Emission Control Burner (ECB): _____
 Comment: _____
 Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404642311	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533801
710500780	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=7533798