

Inspection Photos

April 20th, 2026

Operator: Hilcorp

Location ID: 385893

Inspection Document #: 714003596

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Allison Unit 19



Photo 1. 2024 NAIP imagery of the project area highlighted in blue.

Inspection Photos
Location Name: Allison Unit 19

April 20, 2026 at 10:25 AM
224° SW



Photo 2. View of project area taken from the northern edge facing center.



Inspection Photos
Location Name: Allison Unit 19

April 20, 2026 at 10:26 AM
349° N



Photo 3. Cardinal photo taken from the center of the disturbance facing north.

Inspection Photos
Location Name: Allison Unit 19

April 20, 2026 at 10:26 AM
167° S



Photo 4. Cardinal photo taken from the center of the disturbance facing south.

Inspection Photos
Location Name: Allison Unit 19

April 20, 2026 at 10:29 AM
289° W



Photo 5. View of the project area taken from the eastern edge facing center.
Note: Final reclamation vegetation has not met standards consistent with adjacent reference areas.

Inspection Photos
Location Name: Allison Unit 19



Photo 6. Drone aerial imagery taken of the project area during the time of the inspection.

Inspection Photos
Location Name: Allison Unit 19

April 20, 2026 at 10:32 AM
233° SW



Photo 7. View of gate and existing perimeter fence at the project area.

April 20, 2026 at 10:30 AM
146° SE



Photo 8. Adjacent reference area.

