

Inspection Photos

May 4th, 2026

Operator: Simcoe LLC

Location ID: 312036

Inspection Document #: 714003603

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bellino 1, 3



Photo 1. View of the well pad taken from the access point facing center. Note: Location sign is deteriorating and becoming illegible.

Inspection Photos
Location Name: Bellino 1, 3

May 4, 2026
88° E



Photo 2. Surface owner piping and trailer stored in eastern interim reclamation areas.



Inspection Photos
Location Name: Bellino 1, 3

May 4, 2026
151° SE



Photo 3. View of location fill slope. no Musk thistle was observed during this inspection.



Inspection Photos
Location Name: Bellino 1, 3

May 4, 2026
144° SE



Photo 4. Produced water tank label is peeling and no longer legible.

