

Inspection Photos

May 4th, 2026

Operator: Simcoe LLC

Location ID: 333866

Inspection Document #: 714003604

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bellino 2, 4

May 4, 2026
318° NW



May 4, 2026
335° NW



Photo 1. View of the well pad taken from the access point facing center. Note: Location sign is peeling and becoming illegible.

Inspection Photos
Location Name: Bellino 2, 4




Photo 2. Stained surface material at well head #2 has been removed.

Inspection Photos
Location Name: Bellino 2, 4

May 4, 2026
221° SW



Photo 3. Stained surface material at wellhead #4 has been removed.



Inspection Photos
Location Name: Bellino 2, 4



Photo 4. Produced water tank label is peeling and no longer legible.