

Inspection Photos

May 4th, 2026

Operator: Conoco Phillips Company

Location ID: 385889

Inspection Document #: 714003597

County: La Plata

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Argenta 34-10 31-1



Image © 2025 CNES / Airbus

Photo 1. 2024 NAIP imagery of the project area highlighted in blue and associated access road highlighted in red.

Inspection Photos
Location Name: Argenta 34-10 31-1

May 4, 2026
292° W



Photo 2. View of project area access road.

Inspection Photos
Location Name: Argenta 34-10 31-1



Photo 3. View of temporary plastic wrapped wattle BMPs which remain at the reclaimed well pad access point.

Inspection Photos

Location Name: Argenta 34-10 31-1



Photo 4. View of project area taken from the southern edge facing center.
Note: Location has met final reclamation vegetation standards.



Inspection Photos

Location Name: Argenta 34-10 31-1



Photo 5. Patches of Musk thistle observed throughout location access road.

Inspection Photos
Location Name: Argenta 34-10 31-1



Photo 6. Large patch of Musk thistle remains at location access road access point.

