

KEEGAN PATRICK #1
DEAD CALF ISSUE

APRIL 29, 2026

TIMELINES and PHOTOS

DEAD CALF TIMELINE

-Morning of Wednesday, April 29, 2026:

Lease Operator finds dead calf, very swollen, tangled in Keegan Patrick #1 hog wire fence.

The calf was NOT entangled in a pump jack, as is evident by the clean concrete and the fact that the belt guard was placed on the ground in such a way as to prevent anyone or anything from becoming entangled in the belts. It appears the calf had tried to step through the hogwire, got caught and yanked back, entangling itself in the fence as it thrashed about. Two t-posts were ripped out of the ground, other t-posts were leaning, the hogwire was smashed together and yanked to the west side of the pump jack where the calf laid. Normal operations were not inhibited, and there was no obvious gore besides the swollen, dead calf itself.

Lease Operator immediately shuts down Keegan Patrick #1 pump jack, calls Maralex President.

Lease Operator calls Landowner three times, leaves one voicemail.

Lease Operator proceeds to remove dead calf and assess the situation.

Eventually Landowner arrives, verbally assaults Lease Operator for several minutes. No sign of productive conversation, so Lease Operator leaves. Calls President of Maralex to tell him he left location.

New Maralex personnel arrives to video document the calf and pump jack situation; does not have authority to speak to landowner, so does not. Landowner is still on site.

-Landowner and Maralex President play phone tag this day and next day.

-Thursday, April 30, 2026, Keegan Patrick #3B is also shut down.

-Thursday, April 30, 2026, Landowner files complaint with ECOM.

-Thursday, April 30, 2026, approximately 4:30pm Mr. Labowskie calls Maralex emergency line and reams out receptionist.

-Thursday, April 30, 2026, approximately 5pm, Mr. Labowskie meets Maralex President on site, and landowner drives in behind Labowskie. Landowner refuses to speak to President, instead snaps photo of President and drives on.




-Friday, May 1, 2026 Maralex crew rips out old fencing around both Keegan Patrick #1 and Keegan Patrick # 3B, replaces with cattle wire panels. President and Landowner finally speak on the phone, arrange a time to discuss replacing calf.

Timeline of ECMC and Maralex Interaction



4.30.26

- At approximately 4:30pm, ECMC staff Steve Labowskie calls Maralex emergency line, 970-563-4000, reams out receptionist. Speaks to her for several moments.
- After hanging up with Mr. Labowskie, receptionist calls Maralex President and other Office Staff to inform both of Mr. Labowskie's urgent call.
- At approximately 5pm
 - Maralex President greets Mr. Labowskie on site.
 - Moves to greet Landowner who drove in behind Mr. Labowskie.
 - Landowner refuses to speak to Maralex President, instead snaps a photo of the President on his cell phone and drives passed the President, ignoring the President's question: "You don't want to talk?"

PHONE CALLS FROM LEASE OPERATOR -TO LANDOWNER and TO MARALEX WEDNESDAY, 4.29.26



PHONE CALLS FROM MARALEX PRESIDENT TO LANDOWNER 4.29.26 THROUGH 5.1.26



Gore

Concrete pad shows no sign of gore indicating calf was not crushed by weight. Sprinkles of blood only on vertical of concrete.

Calf was on opposite side of pump unit from belts and not caught in belts.

Fence is mangled and crushed, two t-posts were ripped out of the ground and others bent, apparently by the thrashing of the calf.



Fence destroyed by calf



NEW FENCING



BELT COVERS REINSTALLED

