

INSPECTION PHOTOS

Well: GILA MONSTER FEDERAL 42-21

API #: 05-071-06605

INSPECTION DOC #: 716302320

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 5/5/2026

County: Las Animas




PHOTO 2: WELL SIGN



Network: May 7, 2026 at 11:42:07 AM MDT
Local: May 7, 2026 at 11:42:07 AM MDT
+37.245637,-104.671725

PHOTO 3: LOCATION.



Network: May 7, 2026 at 1:21:08 PM MDT
Local: May 7, 2026 at 1:21:07 PM MDT
+37.245664, -104.671355
106° S

PHOTO 4: WELLHEAD AND EQUIPMENT.



Network May 7, 2026 at 1:23:07 PM MDT
Local May 7, 2026 at 1:23:07 PM MDT
+37.245592, -104.671651
16° NE

PHOTO 5: INTERIM RECLIMATION AREA WEST OF WELLHEAD WILL NEED RE-SEEDED. RE-SEED ALL DISTURBED INTERIM RECLIMATION AREAS PER RULE 1003. CA DATE 7/15/2026.

BOP Test

Pressure Test Date: 4/29/2026 8:16:36 AM

Test Performed By: KR


BOP Serial Number: 0507-027

Set Pressure Target: 150

Test Pressure: **7823.276**

Pressure Drop: **323.2759**


Side Tested: pipe rams





BOP Test

Pressure Test Date: 4/29/2026 8:16:36 AM
Test Performed By: KR
BOP Serial Number: 0507-027
Set Pressure Target: 150
Test Pressure: 7952.586
Pressure Drop: 387.9312
Side Tested: housing test





BOP Test

Pressure Test Date: 4/29/2026 8:16:36 AM
Test Performed By: KR
BOP Serial Number: 0507-027
Set Pressure Target: 150
Test Pressure: 7823.276
Pressure Drop: 387.9312
Side Tested: Blinds

