

Final Reclamation Inspection

April 7, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 323505

Inspection Document #: 718801613

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: MUIRHEAD #1-3
Location ID: 323505



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place and vegetation appears to have established to Rule 1004 standards. However, subsidence was observed at the well location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: MUIRHEAD #1-3
Location ID: 323505



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: MUIRHEAD #1-3
Location ID: 323505



Photo 5. Photo taken of the well location, facing southeast. See comments under Photo 1.



Photo 6. Photo taken of the access road to the well location, facing southeast. Photo illustrates that final reclamation meets Rule 1004 standards along the access road.

Inspection Photos
Location Name: MUIRHEAD #1-3
Location ID: 323505



Photo 7. Photo taken of the reference area to the location, south of the location, facing west. Photo illustrates perennial grass vegetation.