

# Final Reclamation Inspection

April 7, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 323506

Inspection Document #: 718801619

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MUIRHEAD #1-4  
Location ID: 323506



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place and alfalfa and perennial grass vegetation is establishing at the location. However this location does not meet Rule 1004 standards as subsidence was observed at the well site.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: MUIRHEAD #1-4  
Location ID: 323506



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos  
Location Name: MUIRHEAD #1-4  
Location ID: 323506



**Photo 5.** Photo taken of the access road to the well location, facing north. Photo illustrates that final reclamation activities have taken place and alfalfa and perennial grass vegetation has established along the access road.



**Photo 6.** Photo taken of the reference area to the location, south of the location, facing south. Photo illustrates perennial grass and alfalfa vegetation.

