

Final Reclamation Inspection

April 7, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 450378

Inspection Document #: 718801611

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Muirhead 1-1
Location ID: 450378



Photo 1. Photo taken of the tank battery location, facing southeast. Photo illustrates that final reclamation activities appear to have taken place at the location and perennial grass is establishing, but vegetation does not meet Rule 1004 standards.



Photo 2. Photo taken of the tank battery location, facing southwest. See comments under Photo 1.

Inspection Photos
Location Name: Muirhead 1-1
Location ID: 450378



Photo 3. Photo taken of the tank battery location, facing southeast. See comments under Photo 1.



Photo 4. Photo taken of ground cover at the tank battery location, facing southwest. Photo illustrates bare ground and perennial grass.

Inspection Photos
Location Name: Muirhead 1-1
Location ID: 450378



Photo 5. Photo taken of the reference area to the location, east of the location, facing southeast. Photo illustrates perennial grass vegetation.

