

# Final Reclamation Inspection

April 7, 2026

Operator: NOBLE ENERGY INC - 100322

Location ID: 319038

Inspection Document #: 718801615

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: MUIRHEAD #1-1  
Location ID: 319038



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities have taken place and vegetation appears to be establishing to Rule 1004 standards. However, subsidence was observed at the well location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos  
Location Name: MUIRHEAD #1-1  
Location ID: 319038



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: MUIRHEAD #1-1  
Location ID: 319038



**Photo 5.** Photo taken of the well location, facing north. See comments under Photo 1.



**Photo 6.** Photo taken of the reference area to the location, northeast of the location, facing east. Photo illustrates perennial grass and alfalfa vegetation.

