

Final Reclamation Inspection

April 16, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 327703

Inspection Document #: 718801621

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BRATTAIN #2
Location ID: 327703



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) and cheatgrass (*Bromus tectorum*) were observed at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: BRATTAIN #2
Location ID: 327703



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN #2
Location ID: 327703



Photo 5. Photo taken of ground cover at the well location. Photo illustrates bare ground, perennial grass, and russian thistle (*Salsola tragus*).



Photo 6. Photo taken of the access road to the well location, facing south. Photo illustrates that final reclamation activities have taken place along the access road, but vegetation has not established to Rule 1004 standards. Bare ground and weedy annual vegetation including russian thistle (*Salsola tragus*) and cheatgrass (*Bromus tectorum*) were observed along the road.

Inspection Photos
Location Name: BRATTAIN #2
Location ID: 327703



Photo 7. Photo taken of the access road to the well location, facing north. See comments under Photo 6.



Photo 8. Photo taken of the reference area to the location, north of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.

