

# Final Reclamation Inspection

April 16, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328325

Inspection Document #: 718801644

Weld County, CO

Katelyn Mitchem  
Reclamation Specialist, ECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: BELL #L12-18  
Location ID: 328325



**Photo 1.** Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) and cheatgrass (*Bromus tectorum*) was observed at the location.



**Photo 2.** Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos  
Location Name: BELL #L12-18  
Location ID: 328325



**Photo 3.** Photo taken of the well location, facing south. See comments under Photo 1.



**Photo 4.** Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos  
Location Name: BELL #L12-18  
Location ID: 328325



**Photo 5.** Photo taken of ground cover at the well location. Photo illustrates perennial grass, bare ground, and weedy annual vegetation including russian thistle (*Salsola tragus*).



**Photo 6.** Photo taken of the access road to the well location, facing west, away from the location. Photo illustrates that final reclamation activities have taken place, but vegetation establishment does not meet Rule 1004 standards. Weedy annual vegetation including russian thistle (*Salsola tragus*) was observed across the access road.

Inspection Photos  
Location Name: BELL #L12-18  
Location ID: 328325



**Photo 7.** Photo taken of the reference area to the location, northeast of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.

