

Final Reclamation Inspection

April 16, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 336639

Inspection Document #: 718801623

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BELL-63N66W/12SESE
Location ID: 336639



Photo 1. Photo taken of the multi-well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the multi-well location, facing east. See comments under Photo 1.



Inspection Photos
Location Name: BELL-63N66W/12SESE
Location ID: 336639



Photo 3. Photo taken of the multi-well location, facing south.
See comments under Photo 1.



Photo 4. Photo taken of the multi-well location, facing west.
See comments under Photo 1.



Inspection Photos

Location Name: BELL-63N66W/12SESE

Location ID: 336639



Photo 5. Photo taken of ground cover at the multi-well location. Photo illustrates perennial grass and bare ground.



Photo 6. Photo taken of the access road to the well location, facing northeast, towards the location. Photo illustrates that final reclamation activities have taken place along the access road, but vegetation has not established to Rule 1004 standards and bare ground was observed.



Inspection Photos

Location Name: BELL-63N66W/12SESE

Location ID: 336639



Photo 7. Photo taken of the access road to the well location, facing southwest. See comments under Photo 6.



Photo 8. Photo taken of the reference area to the location, north of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.

