

Final Reclamation Inspection

April 16, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 328222

Inspection Document #: 718801652

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BRATTAIN #L12-2J
Location ID: 328222



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN #L12-2J
Location ID: 328222



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN #L12-2J
Location ID: 328222



Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



Photo 6. Photo taken of the well location, facing southwest. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN #L12-2J
Location ID: 328222



Photo 7. Photo taken of the access road to the well location, facing west, away from the location. Photo illustrates that final reclamation does not meet Rule 1004 standards along the access road and bare ground and weedy annual vegetation including cheatgrass (*Bromus tectorum*) were observed.



Photo 8. Photo taken of the reference area to the location, east of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.