

Final Reclamation Inspection

April 16, 2026

Operator: KERR MCGEE OIL & GAS ONSHORE LP - 47120

Location ID: 331610

Inspection Document #: 718801646

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: BRATTAIN L #12-10Ji
Location ID: 331610



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, and perennial grass vegetation is establishing at the location.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN L #12-10Ji
Location ID: 331610



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.

Inspection Photos
Location Name: BRATTAIN L #12-10Ji
Location ID: 331610



Photo 5. Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



Photo 6. Photo taken of the access road to the well location, facing southeast, away from the location. Photo illustrates that final reclamation activities do not appear to have taken place as bare ground and gravel remain across the road.



Inspection Photos
Location Name: BRATTAIN L #12-10Ji
Location ID: 331610



Photo 7. Photo taken of the access road to the well location, facing north, away from the location. See comments under Photo 6.



Photo 8. Photo taken of the reference area to the location, northeast of the location, facing north. Photo illustrates perennial grass and weedy annual vegetation.

