

Final Reclamation Inspection

April 28, 2026

Operator: HIGHPOINT OPERATING CORPORATION – 10071

Location ID: 332703

Inspection Document #: 718801664

Weld County, CO

Katelyn Mitchem
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Location Name: 70 RANCH #21-3, 70 RANCH
#11-3

Location ID: 332703



Photo 1. Photo taken of the well location, facing north. Photo illustrates that final reclamation activities appear to have taken place, and perennial vegetation is establishing, but vegetation establishment does not meet Rule 1004 standards.



Photo 2. Photo taken of the well location, facing east. See comments under Photo 1.



Inspection Photos

Location Name: 70 RANCH #21-3, 70 RANCH
#11-3

Location ID: 332703



Photo 3. Photo taken of the well location, facing south. See comments under Photo 1.



Photo 4. Photo taken of the well location, facing west. See comments under Photo 1.



Inspection Photos

Location Name: 70 RANCH #21-3, 70 RANCH
#11-3

Location ID: 332703



Photo 5. Photo taken of the well location, facing northwest. See comments under Photo 1.



Photo 6. Photo taken of ground cover at the well location. Photo illustrates perennial grass and bare ground.



Inspection Photos

Location Name: 70 RANCH #21-3, 70 RANCH

#11-3

Location ID: 332703



Photo 7. Photo taken of eastern portion of the tank battery location, facing north. Photo illustrates that final reclamation activities have taken place, but vegetation has not established to Rule 1004 standards as weedy annual vegetation including cheatgrass (*Bromus tectorum*), a List C Noxious Weed species, was observed at this portion of the location.



Photo 8. Photo taken of the western portion of the tank battery location, facing west. Photo illustrates that final reclamation activities have taken place and perennial grass vegetation is establishing over a portion of the location. However, bare ground was observed along the northern section of the tank battery.



Inspection Photos

Location Name: 70 RANCH #21-3, 70 RANCH
#11-3

Location ID: 332703



Photo 9. Photo taken of tank battery location, facing east. See comments under Photo 8.



Photo 10. Photo taken of tank battery location, facing south. See comments under Photo 8.



Inspection Photos

Location Name: 70 RANCH #21-3, 70 RANCH
#11-3

Location ID: 332703



Photo 11. Photo taken of ground cover at the tank battery location. Photo illustrates perennial grass, cheatgrass (*Bromus tectorum*), Russian thistle (*Salsola tragus*), and bare ground.



Photo 12. Photo taken of the reference area to the location, east of the location, facing north. Photo illustrates perennial grass which has been partially mowed.

