

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION GV 5-33 Pad

Location ID: 335237



Photo # 7170 From entrance to location




Photo # 7171 Battery sign

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION GV 5-33 Pad

Location ID: 335237



Photo # 7172 Location



Photo # 7173 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION GV 5-33 Pad

Location ID: 335237



Photo # 7174 Location



Photo # 7175 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION GV 5-33 Pad

Location ID: 335237



Photo # 7176 Unused equipment



Photo # 7177 Unused equipment