

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404653716

Date Received:
05/11/2026

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
Gale, Tony	(303) 886-8733	tony@kt-res.com
Adams, Karen	(303) 886-8733	adams@kt-res.com
Baumgras, Dan	(307) 321-3299	Dan@KT-Res.com
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov

ECMC INSPECTION SUMMARY:

FIR Document Number: 715500187

Inspection Date: 06/11/2024

FIR Submit Date: 06/11/2024

FIR Status: _____

Inspected Operator Information:

Company Name: KT RESOURCES LLC

Company Number: 10775

Address: 3381 WESTBROOK LANE

City: HIGHLANDS RANCH State: CO Zip: 80129

LOCATION - Location ID: 336451

Location Name: WRD FEDERAL-62N96W Number: 19SWNW County: _____

Qtrqtr: SWN Sec: 19 Twp: 2N Range: 96W Meridian: 6
W

Latitude: 40.129209 Longitude: -108.214266

FACILITY - API Number: 05-103-00 Facility ID: 336451

Facility Name: WRD FEDERAL-62N96W Number: 19SWNW

Qtrqtr: SWN Sec: 19 Twp: 2N Range: 96W Meridian: 6
W

Latitude: 40.129209 Longitude: -108.214266

CORRECTIVE ACTIONS:

2 CA# 195828

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.

Date: 07/14/2023

Response: CA COMPLETED

Date of Completion: 05/11/2026

Operator Comment: Variance has been submitted in lieu of MIT, Docket No. 260200036, submitted on 2/17/2026. In addition, an Alternate MIT Bradenhead test was conducted on 8/21/2024 with ECMC Inspector Kirby Burchett observing, Document No. 715500572.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 195829

Corrective Action: Perform successful mechanical integrity test. If a successful MIT cannot be performed within 30 day CA time the well must be plugged within 3 months.

Date: 07/14/2023

Response: CA COMPLETED

Date of Completion: 05/11/2026

Operator Comment: Variance has been submitted in lieu of MIT, Docket No. 260200036, submitted on 2/17/2026.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Amber Barnett Signed: _____

Title: Compliance Specialist Date: 5/11/2026 11:20:45 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404653716	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files