

# Inspection Photos

04/30/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335570

Inspection Doc: 719201115

Garfield County, CO

Emily Gaasche  
NW Reclamation Specialist  
ECMC



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 1:** Photos showing an overview of the location looking northwest and southeast, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 2:** Photos showing an overview of the location looking northeast and southwest, respectively.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 3:** Photos showing an overview of tank and separator equipment.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 4:** Photo showing an overview of the wellhead area.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 5:** Photos showing an overview of the northern interim area. Desirable, perennial grasses are present; overall, interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 6:** Photos showing an overview of the southern interim area. Desirable, perennial grasses are present; overall, interim areas are progressing towards 1003 reclamation requirements.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 7:** Photos showing an example of the southern interim area; cheatgrass is encroaching. Weed maintenance is required. Comply with Rule 606.c. and 1003.f.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 8:** Photos showing a patch of bulbous bluegrass, a List C noxious weed, is present in the northeastern interim area.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335570



**Photo 9:** Photos showing some wellhead signage is cracked and discolored, becoming difficult to read. Maintenance is recommended.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources