

Inspection Photos
Location Name: Shaw, Michael S #1
Location ID: 476278



Photo 1: Location from entrance

Photo 2: Tank Battery Sign

Inspection Photos
Location Name: Shaw, Michael S #1
Location ID: 476278



Photo 3: Tank Battery

Photo 4: Capacity installed, NO CONTENTS DISPLAYED

Inspection Photos
Location Name: Shaw, Michael S #1
Location ID: 476278



Photo 5: Nesting removed



Photo 6: Nesting removed

Inspection Photos
Location Name: Shaw, Michael S #1
Location ID: 476278



Photo 7: Vegetation removed

Photo 8: Vegetation removed

Inspection Photos
Location Name: Shaw, Michael S #1
Location ID: 476278



Photo 9: Vegetation removed

Photo 10: Berm repaired

Inspection Photos
Location Name: Shaw, Michael S #1
Location ID: 476278




Photo 11: Vegetation removed

Photo 12: Pilot ignited