

Inspection Photos

04/30/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335572

Inspection Doc: 719201121

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335572



Photo 1: Photos showing and overview of the location looking northwest and southeast, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335572



Photo 2: Photos showing and overview of the location looking northeast and southwest, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335572



Photo 3: Photos showing the eastern fill slopes are dominated by cheatgrass and redstem fillaree, both a List C noxious weed. Desirable, perennial plants are scattered throughout in secondary to tertiary amounts. Weed maintenance is required; comply with Rules 606.c. and 1003.f.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335572



Photo 4: Photos showing the pit to the east of the location is well vegetated.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335572



Photo 5: Photos showing the northern and northeastern interim areas are dominated by cheatgrass and redstem fillaree in the understory, both a List C noxious weed. Desirable, perennial plants are present throughout in secondary to tertiary amounts. Weed maintenance is required; comply with Rules 606.c. and 1003.f.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335572



Photo 6: Photos showing the western and southwestern interrim areas. Overall, interrim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335572



Photo 7: Photos showing the nearby reference area, directly west of the location. The reference area is characterized as a big sagebrush flat.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources