

Inspection Photos

05/08/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 418465

Inspection Doc: 719201124

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 3: Photos showing examples of tank labels that are discolored and peeling; maintenance is required. Comply with 605.h.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 4: An unused/unoccupied vehicle is parked at the location; removal is required pursuant to Rule 606.a.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 5: Photos showing the northern interim area. Interim areas progressing towards 1003 reclamation requirements; noxious weeds are present throughout.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 6: Photos showing bulbous bluegrass (left) and redstem fillaree, both List C noxious weeds that is present throughout the interim area. Redstem fillaree is dominant in the northwestern portion of the interim. Weed maintenance is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 7: Photos showing an example of prickly Russian thistle, cheatgrass, kochia and weedy annual species that are present along the edges of the working pad surface. Weed maintenance is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 8: Photo showing the southwestern interim area with primary to secondary amounts of cheatgrass present.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 418465



Photo 9: Photos showing the eastern and southern interim areas, respectively. Overall, interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources