

Interim Reclamation and Stormwater Inspection

April 28, 2026

Operator: KP KAUFFMAN COMPANY INC - 46290

Location ID: 318548

Well Name: UPRR 42 PAN AM AP #1

Inspection Document #: 718601626

Weld County, CO

Anthony Dunnam
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: UPRR 42 PAN AM AP #1
Location ID: 318548



Photo 1. Looking north across the tank battery location. The location is appropriately sized and the interim area vegetation is reflective of the surrounding reference area.



Photo 2. Looking east across the location.



Inspection Photos
Location Name: UPRR 42 PAN AM AP #1
Location ID: 318548



Photo 3. Photo taken at small pump assembly near VCDs. Stained soil is present around pump. Dark fluid was observed in three buckets around the pump. Leaking fittings were observed on the pump.



Photo 4. Fluid in open top bucket.



Inspection Photos
Location Name: UPRR 42 PAN AM AP #1
Location ID: 318548



Photo 5. Looking north down the east side of the location.



Photo 6. Separators on location inside secondary containment.



Inspection Photos
Location Name: UPRR 42 PAN AM AP #1
Location ID: 318548



Photo 7. Sign on location.



Photo 8. Storage tanks on location.

