

Inspection Photos

05/08/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 417787

Inspection Doc: 719201129

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417787



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417787



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417787



Photo 3: Photos showing an overview of the southern interim area. Interim areas are dominated by bulbous bluegrass, a List C noxious weed. Secondary amounts of smooth brome are present; weed management is required.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417787



Photo 4: Photos showing an overview of the eastern and northern interim areas, respectively. Interim areas are dominated by bulbous bluegrass, a List C noxious weed. Secondary amounts of smooth brome are present; weed management is required.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417787



Photo 5: Photos showing a patch of Russian knapweed, a List B noxious weed, is present on the northern earthen berm along the edge of the working pad surface. Weed management is required.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417787



Photo 6: Vehicle rutting is present and gravel appears sparse on the working pad surface; maintenance is recommended.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 417787



Photo 7: Photos showing the nearby reference area, directly east of the location. Bulbous bluegrass is present in the understory; however, big sagebrush is dominant throughout.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources