

Inspection Photos

05/08/2026

Operator: TEP Rocky Mountain LLC #96850

Location ID: 335266

Inspection Doc: 719201139

Garfield County, CO

Emily Gaasche
NW Reclamation Specialist
ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335266



Photo 1: Photos showing an overview of the location looking north and south, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335266



Photo 2: Photos showing an overview of the location looking east and west, respectively.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335266



Photo 3: Photos showing the eastern interim area. The area is composed of perennial grasses and kochia (light green) as well as bulbous bluegrass, a List C noxious weed.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335266



Photo 4: Photos showing the southern interim area. Cut slopes are well vegetated. Bulbous bluegrass is present in primary amounts throughout the interim area.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP Rocky Mountain LLC #96850

Location ID: 335266



Photo 5: Photos showing kochia is beginning to establish along the edges of the working pad surface (left), and the northern interim area is well established with perennial grasses. Overall, interim areas are progressing towards 1003 reclamation requirements.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources