

# INSPECTION PHOTOS

Well: BUSHMASTER 32-35


API #: 05-071-08155

INSPECTION DOC #: 716302354

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 5/13/2026

County: Las Animas



Network: May 13, 2026 at 1:43:36 PM MDT  
Local: May 13, 2026 at 1:43:36 PM MDT  
+37.302018 -104.717369

PHOTO 2: WELL SIGN



Network: May 13, 2026 at 1:43:02 PM MDT  
Local: May 13, 2026 at 1:43:02 PM MDT  
+37.301887, -104.746978

PHOTO 3: LOCATION.



Network: May 13, 2026 at 1:43:57 PM MDT  
Local: May 13, 2026 at 1:43:57 PM MDT  
+37.302073, -104.747339  
21° NE

PHOTO 4: WELLHEAD AND EQUIPMENT.



**PHOTO 5: AREA OF IMPACTED SOIL NEAR COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,(2).D. CA DATE 6/13/2026.**



Network: May 13, 2026 at 1:49:47 PM MDT  
Local: May 13, 2026 at 1:49:47 PM MDT  
+37.301914, -104.747424  
31.1° SE

**PHOTO 6: AREA OF IMPACTED SOIL NEAR METER HOUSE. Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 6/13/2026.**