

INSPECTION PHOTOS

Well: MACHENZIE FEDERAL 23-2

API #: 05-071-09564

INSPECTION DOC #: 716302342

Operator: EVERGREEN NATURAL RESOURCES LLC

Inspection date: 5/13/2026

County: Las Animas



PHOTO 2: WELL SIGN



Network: May 13, 2026 at 9:48:27 AM MDT
Local: May 13, 2026 at 9:48:27 AM MDT
+37.286771, -104.751128

PHOTO 3: LOCATION.



PHOTO 4: WELLHEAD AND EQUIPMENT.



PHOTO 5: UNUSED EQUIPMENT (2" RISER NEAR METER HOUSE NOT LABELED). **REMOVE OR LABEL RISERS PER RULE 606. CA DATE 6/13/2026.**



Network: May 13, 2026 at 9:55:33 AM MDT
Local: May 13, 2026 at 9:55:33 AM MDT
+37.286676, -104.751405

PHOTO 6: UNUSED EQUIPMENT (2" RISER NEAR METER HOUSE NOT LABELED). REMOVE OR LABEL RISERS PER RULE 606. CA DATE 6/13/2026.



PHOTO 7: UNUSED EQUIPMENT (1" RISER NEAR WELLHEAD NOT LABELED). **REMOVE OR LABEL RISERS PER RULE 606. CA DATE 6/13/2026.**



Network: May 13, 2026 at 9:51:28 AM MDT
Local: May 13, 2026 at 9:51:28 AM MDT
+37.286669, -104.751463
4029 S

PHOTO 8: UNUSED EQUIPMENT (IN GROUND DRIP TANK NO LONGER IN USE). REMOVE UNUSED EQUIPMENT PER RULE 606. CA DATE 6/13/2026.



Network: May 13, 2026 at 9:50:49 AM MDT
Local: May 13, 2026 at 9:50:49 AM MDT
+37.286705, -104.751600
240° SW

PHOTO 9: SMALL PEACES OF TRASH ALL AROUND WELLHEAD AREA AND SOME AROUND METER HOUSE AREA. POLICE ON AND AROUND LOCATION FOR TRASH PER RULE 606. CA DATE 6/13/2026.



Network May 13, 2026 at 9:50:52 AM MDT
Local May 13, 2026 at 9:50:52 AM MDT
+37 286705 -104 751600
-9023 SW

PHOTO 10: SMALL PEACES OF TRASH ALL AROUND WELLHEAD AREA AND SOME AROUND METER HOUSE AREA. POLICE ON AND AROUND LOCATION FOR TRASH PER RULE 606. CA DATE 6/13/2026.



PHOTO 11: SMALL PEACES OF TRASH ALL AROUND WELLHEAD AREA AND SOME AROUND METER HOUSE AREA. **POLICE ON AND AROUND LOCATION FOR TRASH PER RULE 606. CA DATE 6/13/2026.**



Network Ma
Local Ma
Remark: Energy and Ca

PHOTO 12: AREA OF IMPACTED SOIL NEAR WELLHEAD. Cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002,.(2).D. CA DATE 6/13/2026.



Network: May 13, 2026 at 9:50:33 AM MDT
Local: May 13, 2026 at 9:50:33 AM MDT
+37.286728 -104.751575

PHOTO 13: Bradenhead inaccessible or not visible. Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). ALL WELLS SHOULD HAVE ACCESS TO BRHD BY NOW CA DATE 5/15/2026.