

State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



ECMC RECEPTION Receive Date: 04/10/2026 Document Number: 404615475

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with ECMC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, ECMC Policies, and Form Conditions of Approval.

Operator Information

ECMC Operator Number: 10758 Contact Person: Javier Martinez Company Name: OGRIS OPERATING LLC Phone: (719) 8596144 Address: PO BOX 53467 Fax: () City: MIDLAND State: TX Zip: 79710 Email: jmartinez@ogrisop.com

Identification Information

API Number: 05 - - ECMC Facility ID: 292538 Initial Form 19 or 27 Document number: Facility Name: HILL RANCH Facility Number: 18-16 Facility Type: PIT Location QtrQtr: SESE Section: 18 Township: 35S Range: 67W Meridian: 6 County: LAS ANIMAS Field Name: PURGATOIRE RIVER Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: OGRIS OPERATING LLC Agent Name: Javier Martinez Title: Environmental Technician Phone Number: 719-8596144 Email: jmartinez@ogrisop.com

Rule 909.J Inspection Information

Date the Pit was Inspected 03/18/2026 On inspection the Pit was: [X] Unlined [] Lined [] Fenced [] Netted

Sample Location Information:

The following Sample Locations have been reviewed by ECMC Staff:

Facility ID: 265528 Facility Name: HILL RANCH 18-16V Facility Type: Coal Bed Methane Well Location: QtrQtr: SESE Sec: 18 Twp: 35S Range: 67W Meridian: 6 County Name: LAS ANIMAS Latitude: 36.993610 Longitude: -104.922100

Sample Information:

The following Sample Information has been reviewed by the ECMC:

Batch ID: 134355 Document Name: Size of file in bytes: 102912 File Name: HR 18-16 ECMC.xls SampleType: Matrix: Facility ID: 265528 Sample ID: 675534 Sample Name: HR 18-16 Sample Date: 03/18/2026 Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample Project Number: Remediation Number: Complaint Number: NOAV Number: Inspection Number: Spill Number: Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2603228-01

Batch ID: 134356 Document Name: Size of file in bytes: 11425 File Name: HR 18-16 Radium ECMC.xlsx

SampleType: _____ Matrix: _____

Facility ID: 265528 Sample ID: 675535 Sample Name: HR 18-16 Sample Date: 03/18/2026

Collection Point: WellHead Matrix: WATER Pre Post: Rule 909.j initial sample

Project Number: _____ Remediation Number: _____ Complaint Number: _____ NOAV Number: _____

Inspection Number: _____ Spill Number: _____ Laboratory: Green Analytical Laboratories, Inc. Lab Sample ID: 2603223-01

Sample Facility Attachment:

No Facility Attachment

Sample ECMC Well Related:

No Sample ECMC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental Data	The data submitted by the operator can be accessed through the COGIS data system. Laboratory Green Analytical Laboratories, Inc. was added to the radium samples.	05/13/2026
Total: 1 comment(s)		