

Inspection Photos
Location Name: UPRR 42 Pan Am AJ 2
Location ID: 318623



Photo 1 Location access rd.




Photo 2 Wellsite.

Inspection Photos
Location Name: UPRR 42 Pan Am AJ 2
Location ID: 318623



Photo 3 Dead vegetation around wellhead.

Photo 4 Dead vegetation around wellhead.

Inspection Photos
Location Name: UPRR 42 Pan Am AJ 2
Location ID: 318623



Photo 5 Wellhead sign.



Photo 6 Dead vegetation around wellsite.

Inspection Photos
Location Name: UPRR 42 Pan Am AJ 2
Location ID: 318623



Photo 7 Dead vegetation around Ancillary equipment.

Photo 8 Dead vegetation around wellsite.