

Inspection Photos
Location Name: UPRR 42 Pan Am AJ 1
Location ID: 318466



Photo 1 Location access rd.

Photo 2 Well site.

Inspection Photos
Location Name: UPRR 42 Pan Am AJ 1
Location ID: 318466



Photo 3 Dead vegetation around wellhead.

Photo 4 Dead vegetation around wellsite.

Inspection Photos
Location Name: UPRR 42 Pan Am AJ 1
Location ID: 318466



Photo 5 Wellhead sign hidden by dead vegetation.

Photo 6 Dead vegetation around wellsite.

Inspection Photos
Location Name: UPRR 42 Pan Am AJ 1
Location ID: 318466




Photo 7 Dead vegetation around Ancillary equipment.