

Inspection Photos
Location Name: UPRR 43 Pan Am I 16
Location ID: 318369



Photo 1 Location access rd.

Photo 2 Dead vegetation around Wellsite ROW.

Inspection Photos
Location Name: UPRR 43 Pan Am I 16
Location ID: 318369



Photo 3 Dead vegetation around wellhead.



Photo 4 Dead vegetation around wellsite.

Inspection Photos
Location Name: UPRR 43 Pan Am I 16
Location ID: 318369



Photo 5 Wellhead sign is faded.

Photo 6 Dead vegetation around ancillary equipment.

Inspection Photos
Location Name: UPRR 43 Pan Am I 16
Location ID: 318369



Photo 7 Wellhead sign is faded.