

# Inspection Photos

API: 073-06308

Operator: MULL DRILLING COMPANY

Inspection Date: 5/12/2026

County: LINCOLN




**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Center of the location facing north. The desirable vegetation has not established.



## Inspection Photos



**Photo 2.** Center of the location facing west.



## Inspection Photos



**Photo 3.** Center of the location facing south.



## Inspection Photos



**Photo 4.** Center of the location facing east.



## Inspection Photos



**Photo 5.** View of ground cover shows undesirable weeds emerging (Kochia) and bare soil.




## Inspection Photos



**Photo 6.** North side of the location facing south. The desirable vegetation has not established.



## Inspection Photos



**Photo 7.** Facing north toward the surrounding undisturbed reference area.

