

# Inspection Photos

May 11th, 2026

Operator: BMG Drilling Corp.

Location ID: 333585

Inspection Document #: 714003616

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Location Name: La Posta Canyon 1, Dorothy L Gould #3



**Photo 1.** 2024 NAIP Imagery of the well pad (highlighted in blue) and associated access road (highlighted in red).



Inspection Photos

Location Name: La Posta Canyon 1, Dorothy L Gould #3



May 11, 2026  
163° S



**Photo 2.** View of access road facing south towards reclaimed well pad.  
Vegetation is progressing along the access road.

Inspection Photos

Location Name: La Posta Canyon 1, Dorothy L Gould #3

May 11, 2026  
189° S



**Photo 3.** View of the project area taken from the access point facing center. Note: vegetation consists predominantly of mixed perennial grasses.



Inspection Photos

Location Name: La Posta Canyon 1, Dorothy L Gould #3



**Photo 4.** Patches of Musk Thistle observed throughout the project area.

Inspection Photos

Location Name: La Posta Canyon 1, Dorothy L Gould #3

May 11, 2026  
98° E



**Photo 5.** Patch of Cheatgrass observed on the eastern edge of the project area.

Inspection Photos

Location Name: La Posta Canyon 1, Dorothy L Gould #3

May 11, 2026  
312° NW



**Photo 6.** Adjacent reference area.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources