

# Inspection Photos

May 11th, 2026

Operator: Hilcorp

Location ID: 333776

Inspection Document #: 714003623

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Argenta 33-10 34-3, 3A

May 11, 2026  
136° SE



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos

Location Name: Argenta 33-10 34-3, 3A

May 11, 2026  
134° SE



**Photo 2.** View of interim reclamation area facing southeast.



May 11, 2026  
271° W



**Photo 3.** View of location taken from the eastern edge facing center.