

# Inspection Photos

May 11th, 2026

Operator: Logos Operating

Location ID: 325199

Inspection Document #: 714003620

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Bondad 33-10 5

May 11, 2026  
29° NE



Photo 1. View of the well pad taken from the access point facing center.

May 11, 2026  
145° SE



**Photo 2.** View of interim reclamation areas.



Inspection Photos  
Location Name: Bondad 33-10 5



**Photo 3.** View of exposed culvert at access point which is crushed and no longer functioning.



Inspection Photos  
Location Name: Bondad 33-10 5



Photo 4. View of spill pan which is overflowing.

