

# Inspection Photos

May 11th, 2026

Operator: Simcoe LLC

Location ID: 326128

Inspection Document #: 714003618

County: La Plata

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Frank Davis A1

May 11, 2026  
185° S



Photo 1. View of the well pad taken from the access point facing center.

Inspection Photos  
Location Name: Frank Davis A1

May 11, 2026  
182° S



**Photo 2.** View of interim reclamation taken from the northern edge facing south.



Inspection Photos  
Location Name: Frank Davis A1



**Photo 3.** Label is starting to deteriorate, produced water sign has fallen off stand.