

Inspection Photos
Location Name: Lanson Farms Battery
Location ID: 447295



Excavation near the Meter House



Excavation near the Meter House. Groundwater within excavation



Inspection Photos
Location Name: Lanson Farms Battery
Location ID: 447295



Excavation near the Meter House. Groundwater within excavation



Excavation near the Meter House

Inspection Photos
Location Name: Lanson Farms Battery
Location ID: 447295




Discolored soil within stockpile



Oxidized soil along the sidewall of the excavation

Inspection Photos
Location Name: Lanson Farms Battery
Location ID: 447295



Fallen signage

Inspection Photos
Location Name: Lanson Farms Battery
Location ID: 447295





PWV

AST



Inspection Photos
Location Name: Lanson Farms Battery
Location ID: 447295



Weeds

Weeds

